

PRODUCT AFFECTED:

TR-909.

TO SERVICE ENGINEERS:

SUBJECT

TR-909 PROM VERSION UP

PROBLEM

TR-909 will rarely miss-read a \$F8 (MIDI Clock) just after Start data.

REASON

The interval between Start data and the first Clock of MPU-401 is so short (about 1msec).

CHANGES

PROM on TR-909
Ver 1.0 —————> Ver 4.0

NOTE

When you meet above problem, please order us this PROM Ver 4.0 for we have this as Service Parts in our stock.